

Message

From: Nikolaos Kontos [nikolaos.kontos@heidmar.com]
Sent: 4/7/2017 6:40:26 PM
To: master.newactivity@amchkl.com; Nikolaos Kontos [nikolaos.kontos@heidmar.com]
CC: Bulletin [Bulletin@heidmar.com]; OPN@AMCHKL.COM; ISS.Honolulu@ISS-Shipping.com
Subject: RE: NEW ACTIVITY / 5034034 - Honolulu - BUNKER STEM Barber's Point Terminal - Teso

Good Day

we have Nominated 100mt of LSMGO

Best Regards,
Nikolaos Kontos
Sigma Operations Manager

Heidmar, Inc.
20 Glover Ave
Norwalk, CT 06850

Tel: 1-203-662-2620 (Work)
Mobile: 1-203-807-3212
Home: 1-917-442-4174
Fax: 1-203-662-2782 (Work)
Email: Bulletin@heidmar.com
Email: Nikolaos.Kontos@Heidmar.com
Yahoo: Nikolaoskontos49

From: master.newactivity@amchkl.com <master.newactivity@amchkl.com>
To: master.newactivity@amchkl.com; nikolaos.kontos@heidmar.com
Cc: Bulletin@heidmar.com; OPN@AMCHKL.COM; ISS.Honolulu@ISS-Shipping.com
Sent: April 06, 2017 01:42 PM
Subject: RE: NEW ACTIVITY / 5034034 - Honolulu - BUNKER STEM

Ref : ACT17DE038

Date: 06-Apr-2017

TO: Heidmar / Nikolaos Kontons

CC: ISS - Honolulu / Ken Inouye

CC: OPN - AMCL/HKG

FM: New Activity

Dear Kontons,

This is a receipt of acknowledgment for RYE; BUNKER STEM,
which of tasks shall be faithfully managed as your instructions.

+++++

CC: Ken,

Please kindly advise the pilotage for bunkering at Honolulu harbor once
available.

+++++
+

Your kind note/attention for this report would be appreciated

Thanks & Best Regards

Capt. Shen HongFu

Master of New Activity

TEL: +870-773407670 / +852-58034920 (Bridge)

+870-773407670 / +852-58034921 (Captain)

+852-58034922 (CCR)

FAX: +870-783400425

TLX: 463701488 (SAT-C)

Email: master.newactivity@amchk1.com

The E-mail system on board is linked at regular time and may not be monitored all the time, any important or urgent message should be transferred by Tlx, Tel or Fax.

From: Nikolaos Kontos [mailto:nikolaos.kontos@heidmar.com]
Sent: Thursday, April 06, 2017 10:12 PM
To: master.newactivity@amchk1.com
Cc: Bulletin; OPN@AMCHKL.COM; ISS Honolulu ISS-Honolulu
Subject: NEW ACTIVITY / 5034034 - Honolulu - BUNKER STEM

Good Day Captain

The following stem has been concluded on your vessel's behalf.

Vessel name: New Activity
Location: Honolulu
ETA: Apr 09, 2017

Main : 0 mt
Aux : 100-220 mt Max 0.1% LSMGO/DMA – **QTY will be nominated on Friday 4/7 basis intentions on next voyage and expected vessels intake after discharge**

Supplier: Par Petroleum via KPI Oil Associates
Broker: Direct
Buyer: Sigma Tankers

Delivery method: Ex Barge
Payment term: 30

STANDING INSTRUCTIONS

If there is any indication of a problem with quantity or quality during bunkering operations, please notify this office immediately. The best time for us to address discrepancies with the suppliers is before your ship disconnects and/or leaves port.

Notes: Agent to coordinate delivery

To protect the interest of the Pool as well as your Owners we ask that you adhere to the custody transfer sampling procedures outlined in our Bunker Quality Management Program. This program has been approved by all Pool members for the protection of our fleet.

The custody transfer sample for each bunkering is to be taken at the ship's rail via an approved line sampler. Upon completion of bunkering, the sample is to be divided into four equal parts; one for supplier, one to retain onboard, one for DNV testing and one Marpol sample. Please remember to label the Marpol sample and have it counter signed by supplier. To be kept onboard for 12 months.

For dispatching the sample to the correct DNV laboratory, please follow the DNV instructions for quick and smooth dispatch. This will expedite getting the analysis and handling recommendations back to your vessel.

PLEASE MAKE SURE YOU USE THE UNIVERSAL ACCOUNT NUMBER (UAN) 962730810 WHEN FILLING OUT THE DHL AWB.

If asked to sign a receipt for any sample that you did not witness, please sign "For receipt only, sample of unknown origin." In addition, a ship representative should witness and record all barge or meter measurements used by suppliers to determine delivered quantities. Delivered quantities should be compared to ship receipt figures and any difference formally protested. Any difference should also be noted on the delivery receipt and signed for receipt only. Include DNV serial numbers in the BDN, if suppliers do not permit then issue a LOP stating 'refusal to include the DNV serial numbers in the BDN as required per our company's standard procedures'

Finally, if there is any indication of a problem with quantity or quality during bunkering operations, please notify this office immediately.

BEST REGARDS,
KYLE YOUNG
BUNKERING DEPARTMENT

Best Regards,

Nikolaos Kontos

Sigma Fleet Manager

Heidmar, Inc.

20 Glover Ave

Norwalk, CT 06850

Tel: 1-203-662-2620 (Work)

Mobile:1-203-807-3212

Home: 1-917-442-4174

Fax: 1-203-662-2782 (Work)

Email:Bulletin@heidmar.com

Email:Nikolaos.Kontos@Heidmar.com

ICE: NKontos

EvfID:eab8b2eb-f81a-e711-80d3-00155d081d63